



Eric A. Larson Site Vice President 724-682-5234 Fax: 724-643-8069

December 19, 2014 L-14-357

10 CFR 50.73

ATTN: Document Control Desk U. S. Nuclear Regulatory Commission Washington, DC 20555-0001

SUBJECT:

Beaver Valley Power Station, Unit No. 1 Docket No. 50-334, License No. DPR-66 LER 2014-001-01

Enclosed is Licensee Event Report (LER) 2014-001-01, "Beaver Valley Unit 1 Reactor Trip due to Main Unit Transformer Failure." This event was previously reported in accordance with 10 CFR 50.73(a)(2)(iv)(A) on March 7, 2014. This LER supplement provides additional information gained from further internal inspections of the transformer.

There are no regulatory commitments contained in this submittal. Any actions discussed in this document that represent intended or planned actions are described for the NRC's information, and are not regulatory commitments.

If there are any questions or if additional information is required, please contact Mr. William C. Cothen, Manager, Regulatory Compliance at 724-682-4284.

Sincerely,

Eric A. Larson

Enclosure - LER 2014-001-01

cc: Mr. D. H. Dorman, NRC Region I Administrator

Mr. J. A. Krafty, NRC Resident Inspector

Ms. T. A. Lamb, NRR Project Manager

INPO Records Center (via INPO Consolidated Event System)

Mr. L. E. Ryan (BRP/DEP)

IEZZ

NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION APPROVED BY ON									BY OMB NO. 31	50-0104		-	EXPIRES	01/31/2017
(01-2014)  LICENSEE EVENT REPORT (LER)  (See reverse for required number of digits/characters for each block)						Estimated burden per response to comply with this mandatory information collection request. 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects.resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.								
1, FACILITY NAME							2. [	2. DOCKET NUMBER 3. PAGE						
Beaver Valley Power Station Unit Number 1								05000334				1_of 3		
4. TITLE  Beaver Valley Unit 1 Automatic Reactor Trip due to Main Unit Transformer Failure														
5. EVENT DATE			6. LER NUMBER			7. REPORT DA		ATE			FACILITIES INVOLVED			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MONTH	DAY	YEAR	None		DOCK	ET N	UMBER	
01	06	2014	2014	- 001 -	01	12	19	2014	None		DOCK	ET N	UMBER	
9. OPERATING	3 MODE			11. THIS REPO	RT IS	SUBMITTE	D PUR	SUANT T	O THE REQUIREM	ENTS OF 1	0 CFR	§: (C	heck all tha	nt apply)
11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)  20.2201(b)												,		
M	ode 1		l— '' —			20.2203(	a)(3)(ii	)	50.73(a)(2)(i	☐ 50.73(a)(2)(viii)(A)				
1414	Jue i		l —			20.2203(	a)(4)		50.73(a)(2)(ii)(B)		50.73(a)(2)(viii)(B)			
				2203(a)(2)(i)		50.36(c)(	1)(i)(A	)(i)(A)			50.73(a)(2)(ix)(A)			
10. POWER L	EVEL			2203(a)(2)(ii)		50.36(c)(		<b>a</b> )	$\boxtimes$ 50.73(a)(2)(iv)(A) $\square$ 50.73(a)(2)(x)					
				0.2203(a)(2)(iii) 🔲 50.36(c)(2)					☐ 50.73(a)(2)(\		☐ 73.71(a)(4)			
	100			2203(a)(2)(iv)		50.46(a)(3)(ii)			☐ 50.73(a)(2)(v	☐ 73.71(a)(5)				
				2203(a)(2)(v)	$\sqcup$	50.73(a)(			50.73(a)(2)(v			THEI		low or in NRC
			20.2	2203(a)(2)(vi)		50.73(a)(			50.73(a)(2)(v	<u>/)(D)</u>	F	orm 366	SA	
FACILITY NAME				12.	LICE	NSEE CO	NIAC	FOR	HIS LER TELEPHONE NUM	ABER (Incli	ide Are	a Coo	/e\	
			. D	datami Car	ti.				1222111011211011	•			-	
vviiliam Co	William Cothen, Manager, Regulatory Compliance 724-682-4284													
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT														
CAUSE	SYSTEM COM		PONENT FACTURER		REP	ORTABLE O EPIX	_	CAUSE	SYSTEM	COMPON	NENT	FA	MANU- CTURER	REPORTABLE TO EPIX
_ E _	EL	XF	MR	<u>B455</u>		Υ	#	D	BA	65	<b>;</b>	٧	V290	Υ
	14.	SUPPLE	MENTA	L REPORT E	KPEC	TED			15. EXPE SUBMIS		MOI	НΤИ	DAY	YEAR
YES (If yes, complete 15. EXPECTED SUBMISSION DATE)						NO	<u> </u>	DATI						
ABSTRACT (	imit to 140	0 spaces	s, i.e., ap	proximately 15	5 sing	le-spaced	typew	ritten line	s)					
power. An generator to lowering stomplication internal wire replaced.  This event automatic reedwater	automa rip. All t eam ger ons. The nding fau is being actuation pump si	tic rea hree A nerator main alt in th report of systart. A	ctor tri Auxiliar levels transfore 'B' p ed und stems 10 CF	p occurred y Feedwar c. The rea ormer diffe hase wind der 10 CFF listed in (a FR 50.72 n	dueter (Actor (A	e to a m AFW) p trip respination of the due to .73(a)(2 (iv)(B) –	eain t ump pons ectio a die 2)(iv) - (1) vas n	ransfo s autor e was n actua electric (A) as automanade a	(BVPS) Unit rmer differen matically star as expected ation was det breakdown. a condition t atic Reactor tt 1909 hours ter actuation	tial protection ted, as with no termine The trestrip, (6) on Jar	tection experience exp	on medinedinedinedinedinedinedinedinedinedin	nain uni id, due iate caused er has he valid tic Auxi	it to by an been ! !
I														

#### NRC'FORM 366A U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT (LER) **CONTINUATION SHEET** 1. FACILITY NAME 2. DOCKET 6. LER NUMBER 3. PAGE SEQUENTIAL NUMBER RFV YEAR Beaver Valley Power Station Unit Number 1 05000334 2 of 3 2014 001 01

#### NARRATIVE

Energy Industry Identification System (EIIS) codes are identified in the text as [XX].

# CONDITIONS PRIOR TO OCCURRENCE

Unit 1: Mode 1, 100% Power

There were no systems, structures, or components (SSCs) that were inoperable at the start of the event that contributed to the event.

# **DESCRIPTION OF EVENT**

On January 6, 2014 at 1659 hours, Beaver Valley Power Station (BVPS) Unit 1 was operating at 100 percent power. An automatic reactor trip occurred due to a main transformer [XFMR] differential protection [87] main unit generator [GEN] trip. All three Auxiliary Feedwater (AFW) [BA] pumps [P] automatically started as expected due to lowering steam generator [SG] levels. The normal and emergency AC busses [BU] were powered from the offsite supply during this event. Since power to the Emergency Busses was not lost, the Emergency Diesel Generators [DG] were not required to start. The reactor trip response was as expected with no immediate complications. At 1757 hours the plant was stabilized in Mode 3.

At 1848 hours the Control Room received an alarm indicating that the Turbine Driven AFW (TDAFW) pump had stopped. The responding operator reported that the pump had tripped and the two Motor Driven AFW (MDAFW) pumps were operating properly. At 1902 hours the MDAFW pumps were secured. Subsequent investigation revealed that the TDAFW pump had tripped on over-speed due to governor [65] oscillations. (Reference BVPS Unit 1 LER 2014-002-00, Beaver Valley Unit 1 Turbine Driven Auxiliary Feedwater Pump Governor Oscillations Result in Pump Trip, for TDAFW pump details)

## CAUSE OF EVENT

The cause of the main transformer differential trip was determined to be an internal winding fault in the 'B' phase windings due to a dielectric breakdown. This is supported by the results of post fault oil analysis, transformer turns ratio testing, fault recorder data, internal inspections and the "B" Phase coil package inspection. A fault was found on one of the High Voltage coils of the transformer. Due to the extent of damage, the exact cause of the dielectric breakdown cannot be identified. The following conditions may have caused the event to occur: migration of contamination due to overheated oil, a latent manufacturing defect, and/or static electrification.

## ANALYSIS OF EVENT

On January 6, 2014 at 1659 hours, Beaver Valley Power Station (BVPS) Unit 1 was operating at 100 percent power. An automatic reactor trip occurred due to a main transformer differential protection main unit generator trip. All three Auxiliary Feedwater (AFW) pumps automatically started, as expected, due to lowering steam generator levels. The reactor trip response was as expected with no immediate complications.

NRC FORM 366A (01-2014)	LICENSEE I	EVENT REP	•		U.S. NUCLEAR REGULATORY COMMISSION			
1. FACILITY NAME	2. DOCKET	6. I	ER NUMBER		3. PAGE			
Beaver Valley Power Station (	05000334	YEAR	SEQUENTIAL NUMBER	REV NO.	3 of 3			
-		2014 -	001 -	01	3 OF 3			

# NARRATIVE

The plant risk associated with the BVPS Unit 1 automatic reactor trip and an Auxiliary Feedwater actuation, on January 6, 2014, due to a main unit transformer differential trip is considered to be very low. This is based on the conditional core damage probability and conditional large early release probability for the event when considering the actual plant conditions that were present at the time of the event.

Based on the above, the safety significance of the automatic reactor trip and Auxiliary Feedwater actuation event on January 6, 2014, was very low.

#### **CORRECTIVE ACTIONS**

- 1. Replacement of the Main Unit Transformer. (Complete)
- 2. Establish a sequence of operation, for both Units' transformers, that minimizes the potential for static electrification.
- 3. Evaluate training for the appropriate departments on lessons learned from this event.

Completion of the above and other corrective actions is being tracked through the BVPS Corrective Action Program.

# PREVIOUS SIMILAR EVENTS

A review identified the following historical BVPS Unit 1 events involving a failure of the main unit transformer.

BVPS LER 94-005-00 - Main Transformer Bushing Failure Results In Electrical Grid Disturbance and Dual Unit Reactor Trip.

BVPS LER 78-043-00 - Main Transformer Failure and Inadvertent SI

CR 2014-00175, 12779